



Amplified Batteryless Telephone System

VSP 12-Way Quick Guide

About

This document is intended for users of all version 6.0 VSP 12-Way station models (VSP-122, VSP-122P, VSP-211-L, VSP-213-L and VSP-223-L). For further About information, see A100K10873 VSP 12-Way Technical Manual.

Extension Number Setting

Each VSP station must have its own extension number.

To set the extension number:

1. Insert jumpers into pins J2 and J3.
2. Set the DIP switch corresponding to the selected number to the ON position (see Figure 1).




Figure 1: DIP switch for setting VSP extension number. This example shows extension no. 2.

For information on all extension number settings, see section 7: DIP Switch Settings for Extension Numbers in VSP 12-Way Technical Manual.

Number Label

A label strip with numbers 1 to 12 is shipped with each station.

Fix the label with the relevant extension number in the frame next to the text Station no at the front of the station.



Figure 2: Fix extension number label on the upper right corner

Station Operation

To make a call to another station:



1. Set the rotary switch (Line Selector) to the extension number of the station you wish to call.
2. Turn the crank clockwise until a loud beeping tone is heard from the station.
 - About 5 to 6 turns will be required
3. Lift the handset, press the button on the handset and keep it pressed during the entire conversation.

You may now converse with full power and without distortion for a guaranteed period of 20 minutes. After 20 minutes, the conversation period can be extended by turning the crank again.

Troubleshooting

Extension number 11 and 12 do not work. No signal tone.

Possible cause: Jumpers are missing from pins J2 and J3.

Solution: Insert jumpers into pins J2 and J3 (see Figure 1).

VSP station does not receive call. No signal tone.:

Possible cause: No extension number is set.

Solution: Verify that the station has the correct address for the extension number set on the DIP switch (see Figure 1).

VSP station receives calls from two or more lines.



Possible cause: Several extension numbers are set.

Solution: Verify that the station has only one correct address set on the DIP switch (see Figure 1).

When mounting spare part board, no call tone is heard.

Possible cause : Wrong jumper setting.

Solution: When using boards with inductors, remove jumpers from pins J6 and J7/J8 and insert a jumper on pin J9 located to the left of the DIP switches.



Further Information

For further information, use the QR code below to see the A100K10873 VSP 12-Way Technical Manual.





Hear, be heard, and be understood
– every time and everywhere

DOC. NO.

Date 29.11.24

A100K10675

cs@zenitel.com

Zenitel and its subsidiaries assume no responsibility for any errors that may appear in this publication, or for damages arising from the information therein. Zenitel, Vingtor-Stentofon and Phontech products are developed and marketed by Zenitel. The company's Quality Assurance System is certified to meet the requirements in NS-EN ISO 9001. Zenitel reserves the right to modify designs and alter specifications without notice. ZENITEL PROPRIETARY. This document and its supplementing elements contain Zenitel or third-party information which is proprietary and confidential. Any disclosure, copying, distribution or use is prohibited, if not otherwise explicitly agreed in writing with Zenitel. Any authorized reproduction, in part or in whole, must include this legend: Zenitel – All rights reserved.