

Manufacturer's Name: Hewlett Packard Enterprise Company
Manufacturer's Address: 3333 Scott Blvd, Santa Clara, CA 95054, USA

declares under its sole responsibility that the product:

Product Name and/or Model: Please refer to ANNEX I
Regulatory Model Number: APIN0505
Product Options: All

conforms to the following product specifications and regulations:

Safety	Electromagnetic Compatibility	Spectrum
EN 60950-1:2006 + A11:2009	EN 55032:2012 Class B	EN 300 328 V2.2.2
+A1:2010 +A12:2011 +A2:2013	EN 55024:2010	EN 301 893 V2.1.1
EN 62368-1:2014	EN 301 489-1 V2.2.0	EN 300 440 V2.1.1
EN 50385:2017	EN 301 489-17 V3.2.0	
	EN 61000-3-2:2014	
	EN 61000-3-3:2013	
	EN 60601-1-2:2015	
	EN 50155:2017	

Restriction of the use of certain hazardous substances
EN 50581:2012

The product herewith complies with the requirements of the Radio Equipment Regulations 2017 - UK SI 2017 No. 1206, the Restriction of the Use of Certain Hazardous Substances in Electrical and Electronic Equipment Regulations 2012 - UK SI 2012 No. 3032, and carries the UKCA marking accordingly.

Additional Information

This product is assigned a Regulatory Model Number which stays with the regulatory aspects of the design. The Regulatory Model Number is the main product identifier in the regulatory documentation and test reports, this number should not be confused with the marketing name or the product numbers. Any product bearing this Regulatory Model Number that does not carry the UKCA marking is not compliant with all the requirements listed above and may not be placed on the UK market.



San Jose, CA
24.06.2021

Phillip Carranco, Regulatory Manager
Aruba, a Hewlett Packard Enterprise company

Contact for regulatory topics only

EU: HPE, Postfach 0001, 1122 Wien, Austria

US: Hewlett Packard Enterprise, 6280 America Center Drive, San Jose, CA 95002, U.S.A. 844-806-3425

<http://www.hpe.com/eu/certificates>

ANNEX I
Regulatory Model Number: APIN0505

Regulatory Model Number	Product Name and/or Model	HPE Product Number
APIN0505	Aruba AP-505 (EG) Dual Radio 2x2:2 802.11ax Internal Antennas Unified Campus AP	R2H25A
APIN0505	Aruba AP-505 (IL) Dual Radio 2x2:2 802.11ax Internal Antennas Unified Campus AP	R2H26A
APIN0505	Aruba AP-505 (JP) Dual Radio 2x2:2 802.11ax Internal Antennas Unified Campus AP	R2H27A
APIN0505	Aruba AP-505 (RW) Dual Radio 2x2:2 802.11ax Internal Antennas Unified Campus AP	R2H28A
APIN0505	Aruba CM AP-505 (RW) Dual Radio 2x2:2 802.11ax Internal Antennas Unified Campus AP	R2H28ACM
APIN0505	Aruba CM AP-505 (US) Dual Radio 2x2:2 802.11ax Internal Antennas Unified Campus AP	R2H29ACM
APIN0505	Aruba AP-505 (US) Dual Radio 2x2:2 802.11ax Internal Antennas Unified Campus AP	R2H29A
APIN0505	Aruba AP-505 (EG) TAA Dual Radio 2x2:2 802.11ax Internal Antennas Unified Campus AP	R2H35A
APIN0505	Aruba AP-505 (IL) TAA Dual Radio 2x2:2 802.11ax Internal Antennas Unified Campus AP	R2H36A
APIN0505	Aruba AP-505 (JP) TAA Dual Radio 2x2:2 802.11ax Internal Antennas Unified Campus AP	R2H37A
APIN0505	Aruba AP-505 (RW) TAA Dual Radio 2x2:2 802.11ax Internal Antennas Unified Campus AP	R2H38A
APIN0505	Aruba AP-505 (US) TAA Dual Radio 2x2:2 802.11ax Internal Antennas Unified Campus AP	R2H39A

ANNEX II

Software / Firmware	Version
ArubaOS and Aruba InstantOS	8.6.0,0
