

**Manufacturer's Name:** Hewlett Packard Enterprise Company  
**Manufacturer's Address:** 3333 Scott Blvd, Santa Clara, CA 95054, USA

**declares under its sole responsibility that the product:**

**Product Name and/or Model:** Please refer to ANNEX I  
**Regulatory Model Number:** APIN0535  
**Product Options:** All

**conforms to the following product specifications and regulations:**

<b>Safety</b>	<b>Electromagnetic Compatibility</b>	<b>Spectrum</b>
EN 60950-1:2006 + A11:2009	EN 55032:2015 Class A	EN 300 328 V2.2.2
+A1:2010 +A12:2011 +A2:2013	EN 55035:2017	EN 301 893 V2.1.1
EN 62368-1:2014	EN 55024:2010	EN 300 440 V2.2.1
EN 50385:2017	EN 301 489-1 V2.1.1	
	EN 301 489-17 V3.1.1	
	EN 61000-3-2:2014	
	EN 61000-3-3:2013	
	EN 60601-1-2:2015	
	EN 50155:2017	

**Restriction of the use of certain hazardous substances (RoHS)**

EN 50581:2012

The product complies with the requirements of the Radio Equipment Regulations 2017, the Restriction of the Use of Certain Hazardous Substances in Electrical and Electronic Equipment Regulations 2012, and carries the UKCA marking accordingly.

**Additional Information**

This product is assigned a Regulatory Model Number which stays with the regulatory aspects of the design. The Regulatory Model Number is the main product identifier in the regulatory documentation and test reports, this number should not be confused with the marketing name or the product numbers. Any product bearing this Regulatory Model Number that does not carry the UKCA marking is not compliant with all the requirements listed above and may not be placed on the UK market.



Santa Clara , CA  
21.10.2021

Phillip Carranco, Regulatory Manager  
Aruba, a Hewlett Packard Enterprise company

**Contact for regulatory topics only**

Europe: HPE, Postfach 0001, 1122 Wien, Austria

US: Hewlett Packard Enterprise, 11445 Compaq Center West Drive, Houston, Texas, 77070, United States of America (U.S.), 844-806-3425

<http://www.hpe.com/eu/certificates>

**ANNEX I**  
**Regulatory Model Number: APIN0535**

<b>Regulatory Model Number</b>	<b>Product Name and/or Model</b>	<b>HPE Product Number</b>
APIN0535	Aruba AP-535 (EG) Dual Radio 4x4:4 802.11ax Internal Antennas Unified Campus AP	JZ333A
APIN0535	Aruba AP-535 (IL) Dual Radio 4x4:4 802.11ax Internal Antennas Unified Campus AP	JZ334A
APIN0535	Aruba AP-535 (JP) Dual Radio 4x4:4 802.11ax Internal Antennas Unified Campus AP	JZ335A
APIN0535	Aruba AP-535 (RW) Dual Radio 4x4:4 802.11ax Internal Antennas Unified Campus AP	JZ336A
APIN0535	Aruba AP-535 (US) Dual Radio 4x4:4 802.11ax Internal Antennas Unified Campus AP	JZ337A
APIN0535	Aruba AP-535 (EG) TAA Dual Radio 4x4:4 802.11ax Internal Antennas Unified Campus AP	JZ343A
APIN0535	Aruba AP-535 (IL) TAA Dual Radio 4x4:4 802.11ax Internal Antennas Unified Campus AP	JZ344A
APIN0535	Aruba AP-535 (JP) TAA Dual Radio 4x4:4 802.11ax Internal Antennas Unified Campus AP	JZ345A
APIN0535	Aruba AP-535 (RW) TAA Dual Radio 4x4:4 802.11ax Internal Antennas Unified Campus AP	JZ346A
APIN0535	Aruba AP-535 (US) TAA Dual Radio 4x4:4 802.11ax Internal Antennas Unified Campus AP	JZ347A
APIN0535	Aruba CM AP-535 (RW) Dual Radio 4x4:4 802.11ax Internal Antennas Unified Campus AP	JZ336ACM
APIN0535	Aruba CM AP-535 (US) Dual Radio 4x4:4 802.11ax Internal Antennas Unified Campus AP	JZ337ACM

**ANNEX II**

<b>Software / Firmware</b>	<b>Version</b>
ArubaOS and Aruba InstantOS	8.5.0.0 (with some restrictions)
ArubaOS and Aruba InstantOS	8.6.0.0 or later (no restrictions)